Oil Field Environmental Incident Summary

Responsible Party: XTO ENERGY INC. **Well Operator:** XTO ENERGY INC. **Well Name:** LUNDIN FEDERAL 31X-9

Field Name: NORTH FORK Well File #: 17629

Date Incident:7/27/2014Time Incident:0930Facility ID Number:County:MCKENZIETwp:149Rng:97Sec:9Qtr:

Location Description: Light mist of fluid blew E/SE of treater, covering approximately an area of 20'

x 100'.

Submitted By: Kaylan Dirkx Received By:

Contact Person: Kaylan Dirkx

P.O Box 1589 Sidney, MT 59270

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Treater Leak

Release Contained in Dike: No Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	20	Barrels	10	Barrels	10	barrels
Brine	10	Barrels	2	Barrels	2	barrels

Other

Description of Other Released Contaminant:

Inspected: Written Report Received: 2/5/2016 Clean Up Concluded: 8/11/2014

Risk Evaluation:

None

Areal Extent:

Light mist of fluid blew E/SE of treater and covered an area of approximately 100' x 20'.

Potential Environmental Impacts:

Impacted vegetation off site was fenced off and absorbent material was put in place.

Action Taken or Planned:

Free liquids were recovered and returned to production tanks. Impacted soil on location will be removed and hauled to IHD. Off location area (vegetation) will be mowed and disposed at IHD.

Wastes Disposal Location: Indian Hills Disposal.

Agencies Involved:

Updates

Date: 7/29/2014 Status: Reviewed - Follow-up Required Author: Roberts, Kris

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release from a treater leak, sprayed off location. Follow-up is necessary.

Date: 7/31/2014 Status: Inspection Author: Stockdill, Scott

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Arrived on location at 12:30 7/31/14.

Areal extent is larger than is detailed in the incident summary. The impacted grass off of location has been mowed and removed. There is a small amount left on the grass beyond the mowed area, however due to the rough terrain it is not recommended to remediate these areas. The area beyond the remediation efforts should naturally bioremediate. A majority of the released material remained within the lease location. That area is currently being remediated with the impacted soil having been removed and new soil being brought in.

No more follow up is necessary due to minor impacts off of location and the proper remedial steps being taken to prevent further impacts.